

3M™ Perfect-It™ II
Foam Polishing Pad Glaze - Dark
39009/60-4400-9520-0

Applications: Recommended for use to remove compounding swirl marks from all types of refinish or factory applied automotive paints. May also be used to remove fine scratches and wheel marks from paints that do not require compounding. To minimize the possibility of staining, do not apply in direct sunlight or onto a hot surface.

Directions For Use: Use with an air or electric buffer (1000 to 2000 rpm) equipped with a 3M™ Perfect-It™ Foam Polishing Pad.

1. Apply enough glaze to the paint surface to work a two foot by two foot area. To minimize slinging, apply glaze sparingly and spread with the polishing pad before starting the machine.
2. Start the machine and buff using light to medium pressure.
3. Reduce pressure as glaze begins to dry and polish to a high gloss.

Note: If glaze slings onto an adjacent panel, remove glaze spatter with a soft damp cloth as soon as possible or before glazing the next panel.

PROTECT FROM FREEZING

© 3M 2004

3M and Perfect-It are trademarks of 3M Company.