

3M™ Perfect-It™ II
Foam Polishing Pad Glaze - Light
Part Number 39109/60-4400-9527-5
Part Number 39819/60-4400-9510-1

Recommended for use to remove compounding swirl marks from all types of refinish or factory applied automotive paints. May also be used to remove fine scratches and wheel marks from paints that do not require compounding. To minimize the possibility of staining, do not apply in direct sunlight or onto a hot surface.

Directions For Use: Use with an air or electric buffer (1000 to 2000 rpm) equipped with a 3M™ Perfect-It™ Foam Polishing Pad.

1. Apply enough glaze to the paint surface to work a two foot by two foot area. To minimize slinging, apply glaze sparingly and spread with the polishing pad before starting the machine.
2. Start the machine and buff using light to medium pressure.
3. Reduce pressure as glaze begins to dry and polish to a high gloss.

3M and Perfect-It are trademarks of 3M Company.

© 3M 2004